BRUHAT BANGALORE MAHANGARA PALIKE

Inspection Report

1	Name Of Work:	Providing and laying HDPE water line in Mohankumar nagara Block 1 in JP Park ward 17
2	Administration Approval & Date	JC/RRN/AS/2264/2013-14 Dtd: 17.09.2013
3	Technical Sanction Estimate No. & Date	CE/RRN/TS/311/2013-14 Dtd: 18.09.2013
4	Estimate Amount	49,99,000/-
5	Job Code No.	017-14-000032
6	P-Code	P-2201
7	Agreement No and Date:	EE/RRND/Agmt/231/13-14 Dtd: 07.02.2014
8	Work order Number & Date	EE/RRND/WO/231/13-14 Dtd: 07.02.2014
9	Contract Amount as per Agreement	Rs. 53,47,796/-
10	Bill Amount	Rs. 43,33,674=29
11	B.R No. & Date	204/14-15 Dtd: 31.05.2014
12	Agency	K Shivakumar
13	M.B. Number & Page No. of Measurement records	118/13-14 Page No 11742 to 11748
14	Date of Inspection	05.09.2017
15	Enclosures	4 Number of photos taken during inspection
16	Inspection Report	The above said Location has been Inspected by me along with the Concerned person as per EE(RRND) Letter No EE/RRN/PR/414 & /17-18 Dated 1-9-2017. It is observed that the Items indicated in the xerox Copy of MB/XL sheets are not susceptible for measurements, as the nature of work is Laying HDPE water Line, as such the photos taken during the execution of work has been scrutinised and Inspected, it appears that the above work has been done. This has a reference to the NOC issued by Lokayuta Vide Letter No LOK/INV(3)/CT/Crime/60/2014 Dated 1-8-2017

5/9/2017

(R. Sathyanarayana)
Inspection Report Officer.
R. SATHYANARAYANA
INSPECTION OFFICER

EE (RRN) Division, RR Nagara Zone.
ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು -

Scanned by CamScanner